

**Christian Valley Park CSD  
Water Report – May 2022**

**Water Plant Operation and Maintenance**

1. Average flow for the month 0.387 MGD raw water was 1.9 NTU.

**Water Line Repairs and Call Outs**

1. Witt Road
2. 2560 Gayle
3. 3220 CV Road
4. Multiple meter box leaks from meter readings

**Miscellaneous**

1. Oak Springs Ct – Completed
2. Valves and hydrant inspections done

**Capital Improvements**

1. None to report

**Upcoming Work**

1. Rebuild pump station piping (capital improvement project) – will exceed estimated budget

**Storage Tank Project Update**

- a. Tank 2 inspection completed – looked good
- b. Tank 1 warranty repairs were made
  - i. Will coordinate with PRT on reimbursement for repairs and for sprinkler costs on Gayle Lane customer